SCOUTS-L

STOVES

From <@pucc.PRINCETON.EDU:owner-scouts-l@TCUBVM.IS.TCU.EDU> Thu Oct 17 10:30:04 1996

Return-Path: <@pucc.PRINCETON.EDU:owner-scouts-l@TCUBVM.IS.TCU.EDU>

Received: from pucc.PRINCETON.EDU (smtpb@pucc.Princeton.EDU

[128.112.129.99]) by cap1.CapAccess.org (8.6.12/8.6.10) with SMTP id KAA22524; Thu, 17 Oct 1996 10:30:04 -0400

Received: from PUCC.PRINCETON.EDU by pucc.PRINCETON.EDU (IBM VM SMTP V2R2)

with BSMTP id 5161; Thu, 17 Oct 96 10:24:43 EDT

Received: from TCUBVM.IS.TCU.EDU (NJE origin MAILER@TCUBVM) by PUCC.PRINCETON.EDU (LMail V1.2a/1.8a) with BSMTP id 0676; Thu, 17 Oct 1996 10:24:42 -0400

Received: from TCUBVM.IS.TCU.EDU (NJE origin LISTSERV@TCUBVM) by TCUBVM.IS.TCU.EDU (LMail V1.2a/1.8a) with BSMTP id 2137; Thu, 17 Oct 1996 08:01:54 -0600

Received: from TCUBVM.IS.TCU.EDU by TCUBVM.IS.TCU.EDU (LISTSERV release 1.8b)

with NJE id 5743 for SCOUTS-L@TCUBVM.IS.TCU.EDU; Thu, 17 Oct 1996

08:01:21 -0600

Received: from TCUBVM (NJE origin SMTP@TCUBVM) by TCUBVM.IS.TCU.EDU (LMail

V1.2a/1.8a) with BSMTP id 5741; Wed, 16 Oct 1996 09:27:47 -0600 Received: from us1 by tcubvm.is.tcu.edu (IBM VM SMTP V2R2) with TCP; Wed, 16

Oct 96 09:27:42 CST

Received: from n543lan.navo.navy.mil ([128.160.45.102]) by us1 (950511.SGI.8.6.12.PATCH526/8.6.10) with ESMTP id JAA28649; Wed. 16

Oct 1996 09:26:06 -0500

Received: from N543LAN/SpoolDir by n543lan.navo.navy.mil (Mercury 1.21): 16 Oct

96 09:26:44 +1100

Received: from SpoolDir by N543LAN (Mercury 1.21); 16 Oct 96 09:26:25 +1100

Received: from fiddle.navo.navy.mil by n543lan.navo.navy.mil (Mercury 1.21); 16

Oct 96 09:26:19 +1100

Received: by fiddle.navo.navy.mil with Microsoft Mail id

<01BBBB44.14E8EC40@fiddle.navo.navy.mil>; Wed, 16 Oct 1996 09:26:16

-0500

MIME-Version: 1.0

Content-Type: text/plain; charset="us-ascii"

Content-Transfer-Encoding: 7bit

Message-ID: <01BBBB44.14E8EC40@fiddle.navo.navy.mil>

Date: Wed, 16 Oct 1996 09:26:04 -0500

Reply-To: SCOUTS-L - Youth Groups Discussion List

<SCOUTS-L@TCUBVM.IS.TCU.EDU>

Sender: SCOUTS-L - Youth Groups Discussion List

<SCOUTS-L@TCUBVM.IS.TCU.EDU>

From: Garner <garner@N543LAN.NAVO.NAVY.MIL>

Subject: HAZARDOUS RECALL--COLEMAN PEAK 1 APEX STOVE AND

BOTTLE C

X-To: "ARROW-L@TCUBVM.IS.TCU.EDU" < ARROW-

L@TCUBVM.IS.TCU.EDU>

To: Multiple recipients of list SCOUTS-L <SCOUTS-L@TCUBVM.IS.TCU.EDU>

Status: RO X-Status:

The following was cut from a Army and Air Force Exchange bulletin message. Just thought I would pass it on to the list.

YiS.

Dwight

COLEMAN IS VOLUNTARILY RECALLING PEAK 1 APEX STOVE AND BOTTLE COMBO

AND PEAK 1 APEX 22-OZ. REPLACEMENT SINGLE BOTTLE. COLEMAN HAS DISCOVERED A POTENTIAL SAFETY PROBLEM INVOLVING PEAK 1 MODEL 22-OZ.

FUEL BOTTLES. SOME OF THE UNITS CONTAIN A MANUFACTURING DEFECT THAT

MAY ALLOW FUEL LEAKAGE FROM THE THREADS OF THE FUEL BOTTLE NECK

WHEN THE CAP IS IN PLACE OR WHILE THE PUMP/VALVE ASSEMBLY IS ATTACHED

TO THE FUEL BOTTLE. THE FOLLOWING ITEMS ARE INVOLVED: PEAK 1 APEX

A. MODEL 445A700, STOVE, CRC NUMBER 6959472, ITEM NUMBER 491758729,

UPC NUMBER 076501206135.

B. MODEL 450A700, STOVE, CRC NUMBER 0649400, ITEM NUMBER 491758736,

UPC NUMBER 076501204025.

C. MODEL 450-22, 22 OZ. REPLACEMENT BOTTLES (DOLLAR ONLY RECEIVING

CONTRACT).

THE TWO STOVE AND BOTTLE COMBOS COME WITH THE PEAK 1 APEX 22-OZ.

BOTTLE. ONLY PEAK 1 APEX FUEL BOTTLES SHIPPED SINCE APRIL 1996 ARE

INVOLVED. THE BOTTLES CAN BE IDENTIFIED BY A CODE DATE "1-96" STAMPED ON THE BOTTOM OF THE BOTTLE. YOU MAY NEED TO REMOVE A UPC

STICKER FROM THE BOTTOM OF THE BOTTLE TO SEE THE CODE. ALTHOUGH NO

INJURIES OR ACCIDENTS HAVE BEEN REPORTED, COLEMAN HAS FILED A REPORT

WITH THE U.S. CONSUMER PRODUCT SAFETY COMMISSION (CPSC).